## GOVERNMENT OF ANDHRA PRADESH ABSTRACT

General Administration Department – Secretariat Buildings – Special Repairs to E.I. in the O/o Sri K.Sreenivasulu Naidu, Member, Planning Board, Room No.510, 5<sup>th</sup> Floor, J-Block in the premises of A.P. Secretariat –Administrative Sanction – Orders – Issued.

## GENERAL ADMINISTRATION (SB) DEPARTMENT

G.O.RT.No. 783 Dated: 12.03.2015
Read:-

From the Chief Engineer (R&B) Electrical, Errummanzil, Hyderabad. Lr.No.DEE/Elect/ Sectt.Bldgs /AP/2014, Dated: 21.01.2015.

&&&

## ORDER:

In the circumstances reported by the Chief Engineer (R&B) Electrical, Hyderabad in the reference read above and after examination of the matter, administrative sanction is hereby accorded for an amount of Rs.6,50,000-00 (Rupees Six Lakhs Fifty Thousand only) for Special Repairs to E.I. in the O/o Sri K.Sreenivasulu Naidu, Member, Planning Board, Roo0.m No.510, 5<sup>th</sup> Floor, J-Block in the premises of A.P Secretariat, Hyderabad on the responsibility of Chief Engineer (R&B) Electrical, Hyderabad and also subject to production of the work done certificate at the time of issue of L.O.C.

- 2. The expenditure shall be debited to the head of account "2059 Public works 01 Office buildings MH 053 Maintenance and repairs SH(10) Buildings of General Administration Department 270 Minor works 272 Maintenance".
- 3. This order does not require the concurrence of Finance Department in terms of Circular Memo.No.7088/049/A/BG/2000-1, dated 25.10.2002.

(BY ORDER AND IN THE NAME OF THE GOVERNOR OF ANDHRA PRADESH)

MUKESH KUMAR MEENA SECRETARY TO GOVERNMENT (POLL.)

То

The Chief Engineer (R&B) Electrical, Hyderabad.

Conv to:

The Dy.E.E.(R&B) Buillings, Sectt. Sub-Division.

/Forwarded By Order//

SECTION OFFICER.